

ENGLISH

Optical linear measurement sensor with visible red light Quick start guide

There are detailed operating instructions for the linear measurement sensor in addition to the Quick start guide. The Quick start guide is not intended to replace the operating instructions. You can download the operating instructions from www.mysick.com/en/olm100 or www.mysick.com/en/olm100_hi.

You can also download the device description file, control marks, position markers, and the SOPAS Engineering Tool configuration and diagnostics program here.

Safety notes

- Please read the Quick start guide before commencing any work with the optical sensor.
- Connection, mounting, and setting may only be performed by trained specialists.
- When commissioning, protect the device from moisture and contamination.
- Only carry out wiring work when the power status is off.
- Only use screened cables for data transmission.
- Not a safety component in accordance with the EU Machinery Directive.

Correct use

The OLM100/OLM100 Hi optical linear measurement sensor is an opto-electronic sensor and is used for positioning a moving unit by means of a bar code tape.

Commissioning

- 1 Align the bar code tape with a reference edge on the product travel path (e.g., rail) (see Fig. C).
- 2 Affix the bar code tape to a flat, dry, grease- and dust-free surface free of tension, folds, and wrinkles.
- 3 Make the electrical connection (see Fig. B). Connect the cables with the power off.
- 4 Attach the linear measurement sensor to a suitable moving unit using sliding nuts and the fixing holes or T-slots on the back (see Fig. A). Note the distance between the underside of the housing or the vertical centering of the alignment markers and the bar code tape. (see Fig. C).
- 5 Switch on the supply voltage. The "power on" indicator and status indicator LEDs light up green.

Communication interface

Configuration of the sensor takes place via Ethernet interface ④.

— SSI interface:

The sensor supports SSI (Synchronous Serial Interface) — CANopen:

The sensor supports the CiA 301 (CANopen Application Layer and communication profile)

— RS-422/RS-485 interface:

Serial data transmission of the sensor makes it possible to read out the position values and other defined operating data or to change the configuration. All data is transmitted as ASCII characters. Various protocols are available for serial communication.

— RS-485 parameter list for binary protocol type 2 (only valid for OLM100-1005S01):

- Data transmission rate: 62.5 kBd
- Data bit: 9
- Start bit: 1
- Stop bit: 1
- Parity: none

Maintenance


SICK sensors are maintenance-free. We recommend doing the following regularly:

- Cleaning the optical lens surfaces
- Checking the screw and plug-in connections
- Removing contamination from the bar code tape with a damp cloth, without the use of solvents

SICK

8013319/YF09/2015-02/HS_8M

OLM100 OLM100 Hi



Australia Phone +61 3 9457 0600	Österreich Phone +43 (0)22 36 62 28 8-0
Belgium/Luxembourg Phone +32 (0)2 466 55 66	Norge Phone +47 67 81 50 00
Brazil Phone +55 11 3215-4900	Polska Phone +48 22 837 40 50
Canada Phone +1 905 771 14 44	România Phone +40 356 171 120
Ceská republika Phone +420 2 57 91 18 50	Russia Phone +7 495-775-05-30
China Phone +86 4000 121 000	Schweiz Phone +41 41 619 29 39
+852 2153 6300	Singapore Phone +65 6744 3732
Danmark Phone +45 45 82 64 00	Slovenija Phone +386 (0)1-47 69 990
Deutschland Phone +49 211 5301-301	South Africa Phone +27 11 472 3733
España Phone +34 93 480 31 00	South Korea Phone +82 2 786 6321/4
France Phone +33 1 64 62 35 00	Suomi Phone +358-9-25 15 800
Great Britain Phone +44 (0)1727 831121	Sverige Phone +46 10 110 10 00
India Phone +91-22-4033 8333	Taiwan Phone +886-2-2375-6288
Israel Phone +972-4-6801000	Türkiye Phone +90 (216) 528 50 00
Italia Phone +39 02 27 43 41	United Arab Emirates Phone +971 (0)4 8865 678
Japan Phone +81 (0)3 5309 2112	USA/Mexico Phone +1(952) 941-6780
Magyarország Phone +36 1 371 2680	Niederland Phone +31 (0)30 229 25 44

Please find detailed addresses and additional representatives and agencies in all major industrial nations at www.sick.com

SICK AG | 79183 Waldkirch | Germany | www.sick.com

Subject to change without notice
Irrtümer und Änderungen vorbehalten
Sujet à modification sans préavis
Sujeito a alterações sem aviso prévio
Contenuti soggetti a modifiche senza preavviso
Wijzigingen en correcties voorbehouden
Sujeito a cambios sin previo aviso

記載内容につきましては予告なしに変更する場合がございますのであらかじめご了承ください
如有更改,恕不另行通知



Inbetriebnahme

- 1 Barcode-Band an einer Bezugskante des Verfahrenswegs (z. B. Schiene) ausrichten (siehe Abb. C).
- 2 Barcode-Band zug-, falten- und knitterfrei auf eine ebene, trockene, fett- und staubfreie Oberfläche aufkleben.
- 3 Elektrischen Anschluss durchführen (siehe Abb. B). Leitungen spannungsfrei anschließen.
- 4 Linear-Messsensor über die Befestigungsbohrungen oder über die rückseitigen T-Nuten mittels Nutzensteinen an eine geeignete Verfahrenheit montieren (siehe Abb. A). Dabei den Abstand Gehäuseunterkante bzw. die vertikale Zentrierung der Ausrichtmarkierungen zum Barcode-Band beachten (siehe Abb. C).
- 5 Versorgungsspannung einschalten. Die LEDs „power on“ (Betriebsanzeige) und „status“ (Statusanzeige) leuchten grün.

Kommunikationsschnittstelle

Die Parametrierung des Sensors erfolgt über die Ethernet-Schnittstelle ④.

— SSI-Schnittstelle:

Der Sensor unterstützt SSI (Synchronous Serial Interface) — CANopen:

Der Sensor unterstützt die CiA 301 (CANopen Application Layer and communication profile)

— RS-422/RS-485-Schnittstelle:

Die serielle Datenübertragung des Sensors erlaubt es, die Positionswerte und andere definierte Betriebsdaten auszullesen bzw. die Parametrierung zu ändern. Alle Daten werden als ASCII-Zeichen übertragen. Für serielle Kommunikation stehen verschiedene Protokolle zur Verfügung.

— RS-485-Parameterliste Binärprotokoll Typ2 (gilt nur für OLM100-1005S01):



- Baudrate: 62,5 kBd
- Datenbit: 9
- Startbit: 1
- Stoppbit: 1
- Parität: keine

Wartung

SICK Sensoren sind wartungsfrei. Wir empfehlen in regelmäßigen Abständen:


- die optischen Grenzflächen zu reinigen
- die Verschraubungen und Steckverbindungen zu prüfen
- das Barcode-Band bei Verschmutzungen mit einem feuchten Tuch, lösemittelfrei, zu reinigen.

A



- ① Reference axis position measurement
- ② Mounting hole
- ③ Male connector M12, 5-pin/8-pin
- ④ Female connector Ethernet, M12, 4-pin
- ⑤ Status LEDs
- ⑥ T-slot
- ⑦ Alignment mark


B





OLM100	-1001	-1003	-1005	-1005S01	-1006	-1006S02	-1051	-1201	-1201S03	-1203	-1206
1.	SSI	RS-422	RS-485	CANopen	SSI	SSI	SSI	RS-422	CANopen		
2.	0 ... 10,000 m ³										
3.	100 mm ± 20 mm			130 mm ± 20 mm		100 mm ± 20 mm					
4.	30 mm			40 mm		30 mm					
5.	1 mm			0.15 mm		1 mm					
6.	1 ms	5 ms	1 ms	1 ms	5 ms	1 ms					
7.	0.1/1 mm		1 mm	0.1/1 mm							
8.	4 m/s			10 m/s		10 m/s					
9.	10 ... 30 V DC										
10.	≤ 5 V _{SS}										
11.	< 3 W										
12.	LED red (627 nm)										
13.	30,000 lx ³⁾										
14.	IP 65 (EN 60529)										
15.	⚡										
16.	-30 ... +60 °C ^{8) 9)}										

en	de	fr	pt	es	it	nl	ja	zh
1. Interface	Schnittstelle	Interface	Interface	Interface	Interfaccia	Koppeling	インターフェース	接口
2. Measurement length of the distance moved	Messlänge des Verfahrensweges	Longueur de mesure du trajet de déplacement	Comprimento de medição do deslocamento processual	Longitud de medida del trayecto de desplazamiento	Corsa di spostamento	Meetlengte van de verplaatsingweg	搬送経路の測定長	接行程的測量长度
3. Distance to bar code tape	Abstand zum Barcode-Band	Distance à la bande à code barres	Distância até à faixa com código de barras	Distancia hacia la banda de código de barras	Distanza da nastro con codice a barre	Afstand tot de barcode-band	バーコードテープまでの距離	与条码带的距离
4. Bar code tape width	Barcode-Band-Breite	Largueur de la bande à code barres	Ancho de la cinta del código de barras	Larghezza del nastro con codice a barre	Larghezza del nastro con codice a barre	Barcode-bandbreedte	バーコードテープ幅	条码带的宽度
5. Reproducibility ²⁾	Reproduzierbarkeit ²⁾	Reproductibilité ²⁾	Reprodutibilidade ²⁾	Reproducibilidad ²⁾	Riproducibilità ²⁾	Reproduceerbaarheid ²⁾	再現性 ²⁾	可重复性 ²⁾
6. Output rate	Ausgaberate	Vitesse de sortie	Folha refletora	Relación de salida	Tasso di output	Uitvoerpercentage	出力レート	输出率
7. Resolution	Auflösung	Résolution	Resolução	Resolución	Risoluzione	Resolutie	分辨率	分辨率
8. Max. movement speed	Max. Verfahrensgeschwindigkeit	Vitesse de déplacement maxi	Velocidade máx. de deslocamento	Velocidad máxima del desplazamiento	Velocità di spostamento max.	Max. verplaatsingsnelheid	最大搬送速度	最大操作速度
9. Supply voltage V _S ³⁾	Versorgungsspannung U _S ³⁾	Tension d'alimentation U _S ³⁾	Tensão de força U _S ³⁾	Tensión de alimentación U _S ³⁾	Tensione di alimentazione U _S ³⁾	Voedingsspanning U _S ³⁾	電源電圧 U _S ³⁾	电源电压 U _S ³⁾
10. Residual ripple ⁴⁾	Restwelligkeit ⁴⁾	Ondulacion residual ⁴⁾	Ondulação residual ⁴⁾	Ondulación residual ⁴⁾	Ondulazione residuale ⁴⁾	Restrimpel ⁴⁾	残留波紋度 ⁴⁾	剩余波纹度 ⁴⁾
11. Power consumption	Leistungsaufnahme	Puissance absorbée	Consumo de energia	Consumo de potencia	Potenza assorbita	Opgenomen vermogen	消費電力	功率消耗
12. Light source	Lichtsender	Émetteur	Emisor de luz	Emisor luz	Emettitore luminoso	Lichtzender	投光器	发光射器
13. Ambient light immunity	Fremdlichtunempfindlichkeit	Insensibilité à la lumière ambiante	Insensibilidade à luz externa	Insensibilidad a la luz artificial	Insensibilità contro luce esterna	Vreemdlichtongvoeligheid	耐外乱光	抗环境光能力
14. Enclosure rating	Schutzart	Type de protection	Tipo de proteção	Tipo de protección	Tipo di protezione	Beveiligingswijze	保護等級	保护型
15. Protection class	Schutzklasse	Classe de protection	Classe de proteção	Protección clase	Classe di protezione	Beveiligingsklasse	保護クラス	保护级别
16. Ambient operating temperature	Betriebsumgebungstemperatur	Température ambiante	Temperatura ambiente de operação	Temperatura ambiente de servicio	Temperatura ambiente circostante	Bedrijfsomgevingstemperatuur	作動周囲温度	工作环境温度
¹⁾ Dependent on the set resolution and transfer protocol	¹⁾ Abhängig von eingestellter Auflösung und Übertragungsprotokoll	¹⁾ Dépend de la résolution réglée et du protocole de transmission	¹⁾ Dependente da resolução ajustada e protocolo de transferência	¹⁾ Dependiente da resolución ajustada e del protocolo de transferencia	¹⁾ Dipendente dalla risoluzione e dal protocollo di trasmissione impostati	¹⁾ Afhankelijk van de ingestelde resolutie en het transmissieprotocol	¹⁾ 設定された分解能および伝送プロトコルによる	¹⁾ 根据设定的分辨率和传送协议
²⁾ Statistical error 3 σ, no warm-up time required	²⁾ Statistischer Fehler 3 σ, keine Aufwärmzeit erforderlich	²⁾ Erreur aléatoire 3 σ, pas de montée en température nécessaire	²⁾ Errore estadístico 3 σ, ningún tiempo de calentamiento requerido	²⁾ Error estadístico 3 σ, ningún tiempo de calentamiento requerido	²⁾ Errore statistico 3 σ, non è richiesto un tempo di riscaldamento	²⁾ Statische fout 3 σ, geen opwarm-tijd noodzakelijk	²⁾ 統計错误 3σ, ウォームアップ時間不要	²⁾ 统计错误 3σ, 无需预热时间
³⁾ Threshold values, reverse polarity protected	³⁾ Grenzwerte, verpolsicher	³⁾ Valeurs limites, à l'épreuve d'une inversion de polarité	³⁾ Valores limite, protegidos contra inversión de polaridade	³⁾ Valores limite, protegidos contra inversión de polaridad	³⁾ Valori limite, a prova di inversione di polarità	³⁾ Grenswaarden, beveiligd tegen verkeerd polen	³⁾ 限界値、逆極性保護	³⁾ 极限值, 有变极保护
⁴⁾ May not exceed or fall short of V _S tolerances	⁴⁾ Ne dépasser la tolérance sur U _S	⁴⁾ Ne dépasser la tolérance sur U _S ni en plus, ni en moins	⁴⁾ Não ultrapassar as tolerâncias U _S	⁴⁾ No exceder ni por arriba ni por defecto las tolerancias U _S	⁴⁾ Non oltrepassare le tolleranze di U _S	⁴⁾ Mag U _S toleranties niet over- en onderschrijden	⁴⁾ 電源電圧投入値の許容値を上回ることも下回ることも許可されていません。	⁴⁾ 不得超出或低于 U _S 公差
⁵⁾ Typical value at +25 °C ambient temperature	⁵⁾ Typ. Wert bei +25 °C Umgebungstemperatur	⁵⁾ Valeur typique à la température ambiante de +25 °C	⁵⁾ Valor típ. com temperatura ambiente de +25 °C	⁵⁾ Valor típ. a +25 °C de temperatura ambiente	⁵⁾ Valore tipico con temperatura ambiente di +25 °C	⁵⁾ Typ. waarde bij +25 °C omgevings-temperatuur	⁵⁾ 代表値(周囲温度 +25 °C の場合)	⁵⁾ 环境温度 +25 °C 时的典型值
⁶⁾ -30 °C with 30 min warm-up time	⁶⁾ -30 °C mit 30 min Aufwärmzeit	⁶⁾ -30 °C bei 30 min Aufwärmzeit	⁶⁾ -30 °C com 30 minutos de tempo de aquecimento	⁶⁾ -30 °C con un tiempo de calentamiento de 30 min	⁶⁾ -30 °C con 30 min di riscaldamento	⁶⁾ -30 °C bij 30 min opwarmtijd	⁶⁾ -30 °C(ウォームアップ時間30分の場合)	⁶⁾ -30 °C 时, 预热 30 分钟
⁷⁾ Max. 95 % humidity, non-condensing	⁷⁾ Max. 95 % Luftfeuchtigkeit, nicht kondensierend	⁷⁾ Max. 95 % humidité relative, sans condensation	⁷⁾ Max. 95 % de umidade relativa, sem condensação	⁷⁾ Max. 95 % de umidità dell'aria, senza condensazione	⁷⁾ Max. 95 % di umidità dell'aria, senza condensazione	⁷⁾ Max. 95 % luchtvochtigheid, niet condensierend	⁷⁾ 最大湿度95%、露結なし	⁷⁾ 空气湿度最大 95 % 不冷凝

C OLM100-xx0x



Bar code tape height ①	Interval ②	Tolerance
25 mm	13 mm	± 3.5 mm
30 mm	9 mm	± 3.5 mm
40 mm	4 mm	± 8.5 mm
60 mm	-6 mm	± 18.5 mm
100 mm	-26 mm	± 38.5 mm



- en Alignment mark
- de Ausrichtmarkierung
- fr Marque d'alignement
- pt Marcação de alinhamento
- it Indicazione dell'orientamento
- nl Afstelmarkering
- es Marcado de la alineación
- ja 位置合わせマーク
- zh 对准标记

DEUTSCH

Optischer Linear-Messsensor mit sichtbarem Rotlicht Quickstart

Zusätzlich zum Quickstart gibt es ausführlichen Betriebsanleitungen für den Linear-Messsensor. Das Quickstart ersetzt die Betriebsanleitung nicht. Die Betriebsanleitungen können Sie über das Internet www.mysick.com/de/olm100 bzw. www.mysick.com/de/olm100_hi herunterladen.

Zusätzlich können Sie dort die Gerätebeschreibungsdatei, Steuermarken, Positionsmarken und das Parametrier- und Diagnose-Programm SOPAS Engineering Tool herunterladen.

Sicherheitshinweise

- Vor allen Arbeiten mit dem optischen Sensor das Quickstart lesen.
- Anschluss, Montage und Einstellung nur durch Fachpersonal.
- Gerät bei Inbetriebnahme vor Feuchte und Verunreinigung schützen.
- Verdrähtungsarbeiten nur im spannungslosen Zustand.
- Für Datenübertragung nur abgeschirmte Leitungen verwenden.
- Kein Sicherheitsbauteil gemäß EU-Maschinenrichtlinie.

Bestimmungsgemäße Verwendung

Der optische Linear-Messsensor OLM100/OLM100 Hi ist ein optoelektronischer Sensor und wird für die Positionierung einer Verfahrenheit mittels Barcode-Band eingesetzt.

