

English

Photoelectric proximity sensor Operating instructions

Safety notes

- Read the operating instructions before commissioning.
- Connection, mounting, and setting may only be performed by trained specialists.
- Not a safety component in accordance with the EU Machinery Directive.
- UL listed devices in applications in accordance with NFPA 79. Adapters listed by UL with connection cables are available. Enclosure type 1.
- When commissioning, protect the device from moisture and contamination.
- These operating instructions contain information required during the life cycle of the sensor.

Correct use

The WTx23-2 is an opto-electronic photoelectric proximity sensor (referred to as "sensor" in the following) for the optical non-contact detection of objects, animals, and persons. If the product is used for any other purpose or modified in any way, any warranty claim against SICK AG shall become void.

Commissioning

- WTx23-2, WTB23-2: Photoelectric proximity sensor with background suppression: Check the application conditions: Adjust the sensing range and distance of the object or background and the remission capability of the object according to the corresponding diagram [H] (= sensing range, $y =$ sensing range between the set sensing range and its suppression of the background). Δ = sensing range / object remission / background remission. Remission: $6\% =$ black, $18\% =$ gray ($\textcircled{2}$), $90\% =$ white ($\textcircled{3}$) (referring to standard white as per DIN 5033).

The minimum distance (= y) for background suppression can be determined from diagram [H] as follows:

Example: $x = 400 \text{ mm}$, $y = 30 \Rightarrow 30 \text{ mm of } 400 \text{ mm} = 120 \text{ mm}$
That is, the background is suppressed at a distance of $> 520 \text{ mm}$ from the sensor.

WTx23-2: Photoelectric proximity sensor, energetic: Check the application conditions: Adjust the sensing range and the remission capability of the object according to the corresponding diagram [H] (= sensing range, $y =$ operating reserve).

During this process, an object can only be detected in front of a background if the remission capability of the object is significantly higher than that of the background or if the distance between the object and the background is sufficiently long.

- Mount the sensor using a suitable mounting bracket (see the SICK range of accessories).

Note the sensor's maximum permissible tightening torque of 1.3 Nm .

Note the preferred direction of the object relative to the sensor [see A].

- The sensors must be connected in a voltage-free state ($U_0 = 0 \text{ V}$). The information in the graphics [B] must be observed, depending on the connection type:

– Male connector connection: pin assignment

– Cable: core color

Only apply voltage / switch on the power supply ($U_0 > 0 \text{ V}$) once all electrical connections have been established. The green LED indicator lights up on the sensor.

Explanations of the connection diagram (graphic B):

Switching outputs Q and Q' (according to graphic B):

WTx23-2P / K (PNP: load -> M)

WTx23-2S (relay output)

Q: light switching, object will not be detected, relay active

- WTx23-2xx4x, WTB23-2xx6c: Align the sensor with the object. Select the position so that the red emitted light beam hits the center of the object. You must ensure that the optical opening (front screen) of the sensor is completely clear ($\textcircled{1}$). We recommend making the adjustments using a low remission.

WTx23-2xx2x: Align the sensor with the object. Select the position so that the emitted light (not visible) hits the center of the object. The correct alignment is indicated by the green LED indicators. Please refer to graphics C and E. You must ensure that the optical opening (front screen) of the sensor is completely clear. We recommend making the adjustments using an object with a low remission.

- Sensor which is not possible to set WTx23-2xx0x0: The sensor is adjusted and ready for operation.

Refer to graphics C and G to check the function. If the switching output fails to behave in accordance with graphic C, check application conditions. See section Fault diagnosis.

Sensor with potentiometer (WTx23-2xx0x0):

The sensing range is adjusted with the potentiometer (type: 270°). Clockwise rotation: sensing range increased; counterclockwise rotation: sensing range reduced. We recommend placing the switching state in the object, e.g., see graphic F. Once the sensing range has been adjusted, the object is removed from the path of the beam, which causes the background to be suppressed and the switching output to change (see graphic C).

The sensor is adjusted and ready for operation. Refer to graphics C and G to check the function. If the switching output fails to behave in accordance with graphic C, check application conditions. See section Fault diagnosis.

Sensor with teach-in button (WTx23-2xx0x0):

The sensing range is adjusted by pressing the teach-in button. Do not operate the teach-in button using sharp objects. We recommend placing the switching state in the object, e.g., see graphic F. Once the sensing range has been adjusted, the object is removed from the path of the beam, which causes the background to be suppressed and the switching output to change (see graphic C).

The sensitivity (sensing range) is adjusted by pressing the teach-in button. Do not operate the teach-in button using sharp objects. Once the sensitivity is set, remove the object from the beam path. The switching output changes (see graphic C).

The sensor is adjusted and ready for operation. Refer to graphics C and G to check the function. If the switching output fails to behave in accordance with graphic C, check application conditions. See section Fault diagnosis.

Fault diagnosis

Table I indicates which measures are to be taken if the sensor stops working.

Devices with special features

WTx23-2P1121S01: Sensing range can be set between approx. 30 and 400 mm. The range of objects is heavily restricted in the 0 to 30 mm range, with special male connector, 6-pin JST, OHR-H 4K, pin 1+, pin 2: not connected, pin 3: V, pin 4: Q.

WTx23-2P2421S03: Sensing range: $50 \dots 1,300 \text{ mm}$ on white (90% remission), ambient operating temperature: $-30 \dots +60^\circ\text{C}$

WTB23-2P2401S04: Sensing range: $30 \dots 1,600 \text{ mm}$ on white (90% remission), infrared light

WTx23-201521S05: Sensing range: $30 \dots 1,300 \text{ mm}$ on white (90% remission), switching output: 100 mA (20 V AC), current consumption: $\leq 50 \text{ mA}$, response time: $\leq 3 \text{ ms}$, switching frequency: 200 Hz

WTx23-2P2421S06: Sensing range: $50 \dots 1,000 \text{ mm}$ on white (90% remission), response time: $\leq 6.25 \text{ ms}$, switching frequency: 80 Hz

WTB23-2P1121S07: Sensing range: $30 \dots 2,300 \text{ mm}$ on white (90% remission)

WTB23-2P2421S08: Sensing range: $50 \dots 1,100 \text{ mm}$ on white (90% remission), response time: $\leq 6.25 \text{ ms}$, switching frequency: 80 Hz

Disassembly and disposal

The sensor must be disposed of according to the applicable country-specific regulations. Efforts should be made during the disposal process to recycle the constituent materials (particularly precious metals).



8015974.11k4 1019 COMAT

WTx23-2

Australia	+61 (3) 9457 0600	Netherlands	+31 (0) 30 229 25 44
New Zealand	+64 9 415 0459	Phone	+64 9 222 078
Austria	+43 (0) 2386 62288 0	Phone	+64 9 415 0459
Belgium/Luxembourg	+32 (0) 486 55 66	Phone	+47 67 81 50 50
Brasil	+55 11 3215 4900	Phone	+48 22 538 41 00
Canada	+1 905 771 1444	Phone	+40 359 17 11 20
Czech Republic	+420 234 719 500	Phone	+49 261 98 09 90
Chile	+56 2 2774 7430	Phone	+46 10 110 10 00
Denmark	+45 80 2882 3600	Phone	+41 41 619 29 39
Egypt	+20 3 886 2376 6288 0	Phone	+86 2 2376 6288 0
Finland	+358 9 25 15 800	Phone	+86 59 1 888 78849
France	+33 1 64 32 35 00	Phone	+96 2 786 6321/4
Germany	+49 (0) 11 53 01 0	Phone	+34 93 480 31 00
Iceland	+354 500 50 00	Phone	+46 210 682 5100
Ireland	+353 1 215 6300	Phone	+49 215 3 90 00
Italy	+39 02 743 41 00	Phone	+48 22 538 41 00
Japan	+81 3 309 2112	Phone	+44 0172 811121
Malaysia	+603 8080 7425	Phone	+1 800 325 7425
Mexico	+52 473 748 9451	Phone	+65 6744 3732
SICK AG, Erwin-Sick-Straße 1, D-7913 Waldkirch		Detailed addresses and further locations at www.sick.com	

BTx23-201521S05

B2.ind49

Dabei kann ein Objekt vor einem Hintergrund nur detektiert werden, wenn das Remissionsvermögen des Objektes deutlich größer ist als das Remissionsvermögen des Hintergrundes oder der Abstand zwischen Objekt und Hintergrund ausreichend groß ist.

- Den Sensor an einen geeigneten Befestigungswinkel montieren (siehe SICK-Befestigungsprogramm):
- Maximal zulässiges Anzugsdrehmoment des Sensors von 1.3 Nm beachten.
- Anchluss der Sensoren muss spannungsfrei ($U_0 = 0 \text{ V}$) erfolgen. Je nach Anschlussart sind die Informationen in den Grafiken [vgl. B] zu beachten:
 - Steckerschlüssel: Pinbelegung
 - Leitung: Adernfarbe

Erst nach Anchluss aller elektrischen Verbindungen die Spannungsversorgung ($U_0 > 0 \text{ V}$) anlegen bzw. einschalten. Am Sensor leuchtet die grüne Anzeige-LED.

Erklärun

gung

der Schalttafel mit dem Anschlusschema (Grafik B):

Schaltausgang Q bzw. Q' (gemäß Grafik B):

WTx23-2P / K (PNP: Last -> M)

WTx23-2N (PNP: Last -> L)

WTx23-2S (Ausgang Relais)

Q: hellschaltend, Objekt wird nicht erkannt, Relais aktiv

WTx23-2xx4x, WTB23-2xx6x: Sensor auf Objekt ausrichten. Positionierung so wählen, dass der rote Sendeleitstrahl in der Mitte des Objekts ankommt. Es ist darauf zu achten, dass die grüne Öffnung (Teach-In-Taste) auf Seite vom Objekt frei bleibt. Die Einstellung mit einem Objekt von niedriger Remission vorzunehmen. WTB23-2xx4x: Sensor auf Objekt ausrichten. Positionierung so wählen, dass das Infrarotlicht (nicht sichtbar) in der Mitte des Objekts auftreift. Die korrekte Ausrichtung kann über die Anzeige-LEDs erkannt werden. Siehe dazu Grafik C und E. Es ist darauf zu achten, dass die optische Öffnung (Frontschleife) des Sensors vollständig frei ist. Wir empfehlen, die Einstellung mit einem Objekt von niedriger Remission vorzunehmen.

Grafik B

Sensor ohne Einstellmöglichkeit (WTx23-2xx0x0): Sensor ist eingestellt und betriebsbereit.

Zur Überprüfung der Funktionen Grafik C und G heranziehen. Verhält sich der Schalttausgang nicht gemäß Grafik C, Einsatzbedingungen prüfen.

Siehe Abschnitt Fehlerdiagnose.

Grafik C

Sensor ohne Potentiometer (WTx23-2xx0x0):

Mit dem Potentiometer (Art. 270°) den Schaltabstand eingestellt. Drehung nach rechts: Erhöhung des Schaltabstands. Drehung nach links: Verringerung des Schaltabstands. Wir empfehlen, den Schaltabstand in das Objekt zu legen, z. B. siehe Grafik F. Nachdem der Schaltabstand eingestellt worden ist, das Objekt aus dem Strahlengang entfernen, der Hintergrund wird dabei ausgebündelt und der Schalttausgang ändert sich (siehe Grafik C).

Sensor ist eingestellt und betriebsbereit. Zur Überprüfung der Funktion Grafik C und G heranziehen. Verhält sich der Schalttausgang nicht gemäß Grafik C, Einsatzbedingungen prüfen. Siehe Abschnitt Fehlerdiagnose.

Grafik D

Sensor im Teach-In-Taste (WTx23-2xx0x0):

Durch Drücken der Teach-In-Taste wird der Schaltabstand eingestellt. Durch Drehen nach rechts: Erhöhung des Schaltabstands. Drehung nach links: Verringerung des Schaltabstands. Wir empfehlen, den Schaltabstand in das Objekt zu legen, z. B. siehe Grafik F. Nachdem der Schaltabstand eingestellt worden ist, das Objekt aus dem Strahlengang entfernen, der Hintergrund wird dabei ausgebündelt und der Schalttausgang ändert sich (siehe Grafik C).

Sensor ist eingestellt und betriebsbereit. Zur Überprüfung der Funktion Grafik C und G heranziehen. Verhält sich der Schalttausgang nicht gemäß Grafik C, Einsatzbedingungen prüfen. Siehe Abschnitt Fehlerdiagnose.

Grafik E

Sensor im Teach-In-Zeit (WTx23-2xx0x0):

Durch Drücken der Teach-In-Zeit Taste wird der Schaltabstand eingestellt. Durch Drehen nach rechts: Erhöhung des Schaltabstands. Drehen nach links: Verringerung des Schaltabstands. Wir empfehlen, den Schaltabstand in das Objekt zu legen, z. B. siehe Grafik F. Nachdem der Schaltabstand eingestellt worden ist, das Objekt aus dem Strahlengang entfernen, der Hintergrund wird dabei ausgebündelt und der Schalttausgang ändert sich (siehe Grafik C).

Sensor ist eingestellt und betriebsbereit. Zur Überprüfung der Funktion Grafik C und G heranziehen. Verhält sich der Schalttausgang nicht gemäß Grafik C, Einsatzbedingungen prüfen. Siehe Abschnitt Fehlerdiagnose.

Grafik F

Sensor mit mehreren Anwendungen (WTx23-2xx0x0):

Die entsprechenden Anwendungen müssen voneinander unabhängig sein. Die Anwendung, die zuerst eingeschaltet wird, hat Vorfahrt. Wenn die Anwendung, die zuerst eingeschaltet wurde, abgeschaltet wird, kann die andere Anwendung wieder eingeschaltet werden.

Wtx23-2xx0x0

Wtx23-2xx0x0

Wtx23-2xx0x0

Wtx23-2xx0x0

Wtx

